

Table 1
Historic Resources Management Plan
Historic Landscape Survey Summary*

<u>No.</u>	<u>Landscape Element</u>	<u>Physical Character</u>	<u>Management Strategy</u>	<u>Reference</u>	<u>Location</u>
1	Formal Garden	Planted	Rehabilitation	1873 map	Southern entrance to Center Building (building nos. 1, 2)
2 [?] [†]	Flower Beds	Planted	Preservation	1860 map	North of main loop road near Burroughs Cottage (no. 18)
3	Allee	Planted	Preservation	1873 map	From Gatehouse no. 1 towards Willow (nos. 8, 21)
4	Allee	Planted	Preservation	1893 map	White oaks north of B Building (no. 75)
5 [?]	Hedgerow	Planted	Preservation	1893 map	Farm hedgerow east of L Building (near nos. 37, 64, 75)
6 [?]	Shrub Plantings	Planted	Preservation	none given	Shrub planting north of Pine (no. 6)
7	Tree Plantings	Planted	Preservation	1873 map	Holly trees east of Staff Residence no. 3 (near building nos. 21, 27)
8	Tree Plantings	Planted	Preservation	1860 map	Specimen trees north/northwest of Center Building (nos. 1, 2, 3, 4, 5, 6, 8, 18, 21)
9	Tree Plantings	Planted	Preservation	1893 map	Specimen trees at east lawn of Center Building (nos. 2, 4, 30, 44)
10	Tree Plantings	Planted	Preservation	1893 map	Magnolias southwest of rear entry to Center Building (nos. 2, 44)

* This information was adapted from the Historic Landscape Survey Summary included in *St. Elizabeths Hospital Historic Resources Management Plan* (September 1993), prepared for the District of Columbia Office of Business and Economic Development by Devroux & Purnell – Planners, P.C., Betty Bird – Architectural Historian, and Rhodeside & Harwell, Inc. – Landscape. The HRMP was required by the 1989 memorandum of agreement regarding the preservation of St. Elizabeths and identified the 60 landscape features listed in this table to be preserved in future development of the west campus.

[†] The question mark indicates that the current status of this designated landscape element is uncertain. All other designated landscape elements appear to be extant.

Table 1 (continued)
Historic Resources Management Plan
Historic Landscape Survey Summary

<u>No.</u>	<u>Landscape Element</u>	<u>Physical Character</u>	<u>Management Strategy</u>	<u>Reference</u>	<u>Location</u>
11	Tree Plantings	Planted	Preservation	1873 map	Shade trees near location of former West Lodge (nos. 5, 45)
12	Tree Planting	Planted	Preservation	1893 map	Shagbark hickory near Detached Dining Hall and Kitchen (nos. 33, 34)
13	Tree Plantings	Planted	Preservation	1860 map	Perimeter willow oaks north of Gate no. 2 (near nos. 23, 24, 78)
14	Tree Plantings	Planted	Preservation	1860 map	Lawn plantings east of Allison Complex (near nos. 23, 24, 32, 36, 37)
15 [?]	Plantings	Planted	Preservation	none given	Tree plantings at entrances to A, B, and C Buildings (nos. 73, 74, 75)
16	Tree Plantings	Planted	Preservation	1927 map	Shade trees at Gatehouse no. 2 (no. 78)
17	Tree Plantings	Planted	Preservation	1873 map	Shade trees at promontory lookout
18	Woods	Natural	Preservation	1860 map	Western slopes toward Anacostia River (near nos. 15, 60, 66, 67, 68, 118)
19	Underpass	Built	Rehabilitation	1902 annual report 1908 map	Pedestrian connection to East Campus (near nos. 69, 70, 71)
20 [?]	Road (unpaved)	Built	Rehabilitation	1860, 1873 maps	Carriage trail at southwestern property line
21	Road (unpaved)	Built	Rehabilitation	none given	West of Ice Plant (near nos. 49, 52)
22	Scenic Drive	Built	Preservation	1893 map	Loop road to promontory
23	Scenic Drive	Built	Preservation	1860, 1873 maps	Main loop road at upper plateau/portion of Lowlands
24	Scenic Drive	Built	Preservation	1908 map	Loop road at Quadrangle (near nos. 37, 38, 60, 64, 66, 67, 73, 74, 75)
25	Entrance Drive	Built	Rehabilitation	1920 map	Entrance drive at Gatehouse no. 2 (near nos. 76, 77, 78)

Table 1 (continued)
Historic Resources Management Plan
Historic Landscape Survey Summary

<u>No.</u>	<u>Landscape Element</u>	<u>Physical Character</u>	<u>Management Strategy</u>	<u>Reference</u>	<u>Location</u>
26	Road (paved)	Built	Rehabilitation	1893 map	Road to Greenhouse (nos. 20, 21)
27	Road (paved)	Built	Rehabilitation	1907 annual report, 1908 map	East of A, B, C, and M Buildings (nos. 72, 73, 74, 75)
28	Road (paved)	Built	Rehabilitation	1893 map	South of Staff Residence no. 4 (no. 76)
29	Walkway (paved)	Built	Preservation	1908 map	Parallel to main loop road (near nos. 1, 21)
30	Walkway (paved)	Built	Preservation	1899 map	At lawn areas south of Center Building
31	Walkway (paved)	Built	Rehabilitation	1884 map	Site of former West Lodge entrance (near nos. 3, 5, 45)
32	Walkway (paved)	Built	Preservation	none given	West of Allison A towards Atkins Hall (near nos. 25, 26, 31)
33	Walkway (paved)	Built	Preservation	1873 map	At base of Center, Holly, Linden, and Detached Nurses (nos. 1, 2, 3, 4, 5, 6, 8, 28, 29, 30)
34	Walkway (paved)	Built	Preservation	1907 annual report	South of L Building (near nos. 64, 67)
35	Walkway (paved)	Built	Preservation	1905, 1907 annual reports, 1947 map	Connects E Building toward L Building (nos. 68, 69)
36	Gazebo	Built	Preservation	1883 annual report	East of Allison C (no. 24)
37	Gazebo	Built	Preservation	1883, 1895 annual reports	South of Home and Relief Buildings (nos. 32, 36)
38	Tennis (lawn)	Built	Preservation	none given	Northwest of Center Building
39	Wall (freestanding)	Built	Preservation	1855 annual report	Perimeter of hospital to Gatehouse no. 2 (near nos. 19, 20, 21, 78)
40	Wall (freestanding)	Built	Preservation	1910 map	Perimeter of hospital to Building Q (no. 68)
41	Wall (retaining)	Built	Preservation/ Rehabilitation	none given	East of drive at Greenhouses (no. 20)

Table 1 (continued)
Historic Resources Management Plan
Historic Landscape Survey Summary

<u>No.</u>	<u>Landscape Element</u>	<u>Physical Character</u>	<u>Management Strategy</u>	<u>Reference</u>	<u>Location</u>
42 [?]	Wall (retaining)	Built	Preservation	none given	At the site of former West Lodge (near nos. 3, 5, 45, 46)
43	Wall (retaining)	Built	Preservation	1910 map	At the site of the Toner Building (near nos. 64, 67)
44	Iron Fence	Built	Preservation	1873 map	South side of Center Building
45 [?]	Iron Railing	Built	Preservation	none given	East of Bakery, along path from Center Building (nos. 44, 45)
46 [?]	Iron Railing	Built	Preservation	none given	At southern entrance to Center Building
47	Civil War Cemetery	Built	Preservation	1873 map	West facing slope from Staff Residence no. 1 (no. 15)
48 [?]	Bollard	Built	Preservation	none given	At Center Building turnaround (no. 1)
49 [?]	Iron Railing/ Balcony	Built	Preservation	none given	At windows of A, B, and C Buildings facing quadrangle
50 [?]	Foundation	Built	Preservation	1860 map	Northwestern slope towards Anacostia River
51 [?]	Foundation	Built	Preservation	1860 map	Site of West Lodge (near nos. 3, 5, 44, 45)
52	Fountain	Built	Preservation	1873 map	Flower garden at southern entry to Center Building
53	Fountain	Built	Preservation	none given	East of rear entry to Hagan Hall (no. 38)
54	Curb	Built	Preservation	1907 annual report	Roadway at Gatehouse no. 2 (no. 78)
55 [?]	Grate	Built	Preservation	1910 map	At Toner/Oaks Complex Roadway
56	Stairway	Built	Preservation	none given	From Construction Shops to Ice Plant (nos. 49, 52)
57	Stairway	Built	Preservation	none given	Loading dock in vicinity of West Lodge site

Table 1 (continued)
Historic Resources Management Plan
Historic Landscape Survey Summary

<u>No.</u>	<u>Landscape Element</u>	<u>Physical Character</u>	<u>Management Strategy</u>	<u>Reference</u>	<u>Location</u>
58 [?]	Stairway	Built	Preservation	1873 map	At western lawn of Center Building
59	Patio	Built	Preservation	none given	Between Holly and Detached Nurses (no. 30)
60	Railroad Track Bed	Built	Rehabilitation	1908 map	West of Power Plant to northern property line (nos. 118 and 118A)